


Digital readout

TSMAX



Supplier/ manufacturer:

Address:

Telephone:

Fax:

email :

www:

ver.: 200217



Öchsner Messtechnik GmbH
Schulzengasse 17
97291 Thüngersheim
Tel. +49 9364 817605-0
Fax +49 9364 817605-26
info@oemt.de • www.oemt.de

• präzise • zuverlässig • individuell •

Contents

Specification readout.....	4
Technical Parameters	4
Description and connection of connector type D-SUB 9 socket	4
Electric specification of sensor signals: signal TTL 5 V.....	5
Digital readout scheme.....	5
Initial screen	6
Menu	8
Angle.....	8
Centre of abscissa.....	9
Half.....	10
Scale	11
Tool	13
Milling machine	14
Lathe.....	15
Grinder	15
Calculator	15
Holes on the line	17
Machining	18
Templates	19
Holes on the circle.....	20
Machining	21
Templates	21
Holes on the nut	22
Machining	22
Templates	23
Programmable points	23
Machining	23
Templates	24
Angle of lines	24
Circle centre	24
Machining	25
Setting	26
Basic setting	27
Setting the axes	29
Axis mode	31
Direction.....	32
Encoder resolution	32
Display resolution	32
Linear correction.....	32
Resetting after 360°.....	33
Moving to the reference point.....	33
Machine reference.....	33
Moving to the machine reference.....	34
Averaging	34
Tolerance	34
Feed speed.....	34
Axes adding.....	35
Programmable buttons	35
Extending functions	37

Touch probe.....	37
Setting	39
Calibration on the circle	39
Centre of abscissa.....	41
Circle centre	43
Workpiece centre.....	44
Workpiece edge	46
System update	48
System restart.....	52

Specification readout

Technical Parameters

Supply voltage	24 V DC
Input MAX	24 kW
Operating environment humidity	Max. 85 % at 45 °C, without condensation
Temperature of operating environment	10 °C to 50 °C
Device case	200 x 150 x 40 mm
Weight	1.8 kg
Definition	According to used sensor
Display	Colour, touch, diagonal 7"

Description and connection of connector type D-SUB 9 socket




Fig. 1: D-SUB socket

Contact number	Signal
1	-A
2	0V
3	-B
4	Not connected
5	-Z
6	A
7	+5V
8	B
9	Z

Electric specification of sensor signals: signal TTL 5 V




Fig. 2: Electric specification of sensor signals

Digital readout scheme




Fig. 3: Digital readout scheme

Initial screen

- ⑩ The first screen is displayed after starting the whole system and program TSMAX.
- ⑩ Description fig. 4: Initial screen
 - 1) Actually selected scale and switching between the saved scales.
 - ✦ The user can create own scales with set offsets and then just press buttons on the main screen (see chapter **Chyba! Záložka není definována.**).
 - ✦ It also includes the switching between absolute and incremental mode – button „**Abs/Inc**“.
 - 2) Display of actual tool.
 - ✦ The miller is marked „**F**“, lathe „**S**“ and grinder „**B**“ followed by the order number from the list of created tools (for more see chapters **Chyba! Záložka není definována.**).
 - 3) The mode display – Absolute/Incremental (Abs/Inc).
 - ✦ It is switched by button „**Abs/Inc**“ on the lower screen side.
 - ✦ In case of selecting the incremental mode, the displayed values from the encoder are displayed with red letter identically to the scales (see chapter **Chyba! Záložka není definována.**).
 - 4) Shift speed.
 - ✦ It is possible to set different display speed for every axis or switch off the speed indicator – do not display (for more see chapter **Chyba! Záložka není definována.**).
 - 5) Display of values from the encoders.
 - 6) The buttons for setting or resetting the value.
- ⑩ The initial screen for the miller and grinder is identical. The lathe includes the display of button for the selection of value display from the sensors as radius (**Rad**) or diameter (**Dia**). Setting the device type is performed in basic setting (see chapter **Chyba! Záložka není definována.**).
- ⑩ The last three buttons (in this case „**Scale**“, „**Tools**“, „**Calculator**“) are programmable and they can include another selection (see chapter **Chyba! Záložka není definována.**).

<	Scale 1	>	Tool	F1	Mode	Abs
X	83.745	X	Xo			
Y	113.380	Y	Yo			
Z	22.995	Z	Zo			
W	27.985	W	Wo			
Menu Abs/Inc Scale Tool Calculator						

Fig. 4: Initial screen

<	Scale 1	>	Tool	S1	Mode	Abs
X	Dia 0.0 83.745	X	Xo			
Y	0.0 113.380	Y	Yo			
Z	22.995	Z	Zo			
W	27.985	W	Wo			
Menu Abs/Inc Scale Tool Calculator						

Fig. 5: Initial screen – switching diameter/ radius for the device type lathe

1. Menu

- ⑩ Pressing the button „**Menu**“ displays the option with functions and setting. If in the mode for the grinder or the lathe, the buttons are not displayed „<“ a „>“ for other functions.
- ⑩ If in the mode for the miller and the buttons are used for the selection of other functions („<“ and „>“), the extension functions are displayed (see fig. 7: The extension menu functions for the device type miller).




Fig. 6: Function menu




Fig. 7: The extension menu functions for the device type miller

Angle

A point
X 0.000
Y 0.000
Z 0.000

Settings
Units **deg** **Change**
Selection of **X** **Change**

B point
X 0.000
Y 0.000
Z 0.000

Angle measurement
Y 0.000
Z 0.000

Back **Main screen**

A point
B point
Reset

Fig. 8: Function for searching the angle between the line (abscissa) and the selected level

Centre of abscissa

- ⑩ The function searches for the abscissa centre which is defined by two points.
- ⑩ At first it is necessary to move to required coordinates and pressing buttons „**Point A**“, the actual coordinate is used for point A for calculation.
- ⑩ It is also performed for point B.
- ⑩ It is automatically used for the calculation of the centre coordinate.
- ⑩ Button „**Reset**“ returns everything into the initial setting.

Centre of line

A point

X

0.000

Y

0.000

Z

0.000

B point

X

0.000

Y

0.000

Z

0.000

Centre

X

83.745

Y

113.380

Z

22.995

A point

B point

Reset

Back

Main screen

Fig. 9: Function for searching the abscissa centre between two points

Half

- ⑩ The function which sets the half in individual axes from the actual value.
- ⑩ Half can be set separately for every axis.
- ⑩ Click on button „**Polovina**“ (half) for the defined axis and value for the axis reduce by one half.

Half		
X	83.745	Half
Y	113.380	Half
Z	22.995	Half
W	27.985	Half
Back Main screen		

Fig. 10: Function half

- ⑩ This change is reflected in all program functions where the axis is displayed.

Scale

- ⑩ Scale is used for entering individual axes values.
- ⑩ It adds the calculated offset to the value from the encoder so the result is the defined value
- ⑩ In the review screen (see fig. 11: The scale – the review screen of the scales indicates which scale is active (top right), which scale is actually displayed, and how many scales are created.
- ⑩ It is possible to set a note and value for every axis for every scale.
- ⑩ Use buttons „**Predchozi**“ (former) and „**Dalsi**“ (next) to switch between individual scales for the display.
- ⑩ Button „**Aktivovat**“ (activate) activates the defined scale. This includes the set offset in the calculation for the actual values from the encoders. Switching and activation of scales is also on the main screen by means of buttons „<“ and „>“ (see chapter **Chyba! Záložka není definována.** - point 1).
- ⑩ Buttons „**Novy**“ (new) and „**Upravit**“ (edit) start new or edit the existing scale.
- ⑩ Button „**Smazat**“ (delete) deletes the selected scale „**Smazat vse**“ (delete all) removes all saved scales.
- ⑩ Button „**Seznam ABS**“ (List ABS) displays all absolute scales and their values (see fig. 12: Scale – list of saved scales). This list enables to activate the selected scale by means of button „**Zvolit**“ (select).
- ⑩ If we select incremental mode (button „**Abs/Inc**“), on the initial screen, the values will be red. This mode is for every scale. It is possible to set values for absolute and incremental mode and after activating the scale it is possible to switch between them.

Scale		Current scale: 1
Displayed position:	1	Activate New Modify
Number of positions:	1	
Label:		
X	83.745	Delete Delete all
Y	113.380	
Z	22.995	
W	27.985	
Previous List of ABS Next		
Back		Main screen

Fig. 11: Scale - Review screen

Milling machine

- ⑩ Miller parameter setting
- Tool diameter
- Measuring as diameter/radius
- Selected plane
- Machining direction – according to the former parameters, it adds or deducts the value of the diameter/ radius to the elected axis (axes).
- In this type of device, the menu displays functions for drilling holes, angle search between the lines or searching for the circle centre (see fig. 7: The extension menu functions for the device type miller).

Tool **Current tool: 1**

Number of saved tools:	1	Deactivate New Modify
Displayed tool:	1	
Type of the tool:	Milling machine	
Label:	Label	
Tool diameter:	1.000	Delete Delete all
Measure as:	Diameter	
Plane:	XZ	
Direction of tooling:	+Y	

Fig. 13: Tool – review screen for tool type miller

Lathe

- ⑩ It is possible to set the machine shift for individual axes.
- ⑩ The values can be changed for every axis separately.
- ⑩ In case of selecting the device type lathe or grinder cannot use the extending functions (see fig. 7: The extension menu functions for the device type miller).

The screenshot shows a software interface for reviewing tool settings. At the top, the title 'Tool' is on the left and 'Current tool: 1' is on the right. Below the title, there are several input fields and buttons. The 'Number of saved tools' field contains the value '1'. The 'Displayed tool' field also contains '1'. The 'Type of the tool' field contains 'Lathe'. The 'Label' field contains 'LABEL'. Below these, there are three rows for axis settings: 'Osa X' with value '2.000', 'Osa Z' with value '0.000', and 'Osa Z₀' with value '2.000'. To the right of these fields are five buttons: 'Deactivate', 'New', 'Modify', 'Delete', and 'Delete all'. At the bottom of the screen, there are five buttons: 'Previous', 'List', 'Next', 'Back', and 'Main screen'.

Fig. 14: Tool – review screen for tool type lathe

Grinder

- ⑩ The same setting as for the lathe.

Calculator

- ⑩ Calculator for individual calculators (see fig. 15: Calculator).
- ⑩ It contains goniometric functions.
- ⑩ Top panel (yellow) is used for the display of entry history and the panel below is used for the display of the results, inter-results, and entering the actual value.
- ⑩ Button „**Prenest**“ (transfer) is used for transferring the values from individual axes to the calculator or vice versa from the calculator to individual axes (see fig. 16: Calculator – value transfer).
 - 1) If I calculate something on the calculator, it is possible to use buttons „X“ to „W“ to transfer the result on the selected axis.
 - 2) It displays the selected values from the encoder, which can be transferred to the calculator, and used for calculation.

Calculator

7 8 9 + sin() arcsin()
 4 5 6 - cos() arccos()
 1 2 3 * tan() arctan()
 +/- 0 . / sqrt() pi()

Back Main screen Transfer Delete =

Fig. 15: Calculator

Transfer of value

Value from calculator 0.000

To axis: X Y Z W

Value of the axis

X	83.745	To calculator
Y	113.380	To calculator
Z	22.995	To calculator
W	27.985	To calculator

Back Main screen

Fig. 16: Calculator – value transfer

Holes on the line

- ⑩ It is used for drilling holes on the line.
- ⑩ At first, select the plane where individual holes shall be drilled.
- ⑩ Set the centre coordinates for drilling. It is possible to set any coordinates or the actual coordinates using button „**Nastavit aktualni stred**“ (set actual centre) (see fig. 18: Hole drilling on line – edit one point from the scene).
- ⑩ Select the number of holes for drilling
- ⑩ Set the spacing of the holes and their turning.




Fig. 17: Drilling holes on the line

- ⑩ Automatically re-draws the scene with the display how the task shall look like.
- ⑩ Every entered hole can be edited independently – shift in defined plane axes, set the distance from the centre or the turning angle. This option is achieved by marking the hole in the scene (finger or stylus). Marked hole is green (see fig. 18: Hole drilling on line – edit one point from the scene).
- ⑩ **Caution** during every change of the setting the scene is re-drawn. If for example one hole is shifted to other than defined entry (manually, see point) and then the setting changes, it is automatically re-drawn!
- ⑩ The hole can be deleted from the scene using button „**Odstranit**“ (delete).
- ⑩ After returning to the initial setting, it is possible to use button „**Zpet**“ (back) on the right or mark a location where no hole is drawn in the scene.
- ⑩ As soon as all parts are entered, press button „**Obrabeni**“ (machining) to get back to the machining mode where individual holes can be drilled.




Fig. 18: Hole drilling on line – edit one point from the scene

Machining

- ⑩ Use buttons „Predchozi“ (former) and „Dalsi“ (next) to switch between individual holes (see fig. 19: Hole drilling on line – machining mode).
- ⑩ The right side displays the coordinates between the tool (red cross) and marked hole (green).
- ⑩ According to the selected plane (in this case XY) it is necessary to load in such way the coordinates X and Y displayed zero. It indicates that the tool is placed exactly above the hole.
- ⑩ Axes Z and W are for orientation purposes and can be reset (set to zero), for better depth designation.




Fig. 19: Hole drilling on line – machining mode

Templates

- ⑩ It includes a function for the administration of individual settings which can be reached by button „**Sablony**“ (template) in top right.
- ⑩ The template administration opens (see fig. 20: Hole drilling on line – templates).
- ⑩ As soon as all parameters are set and they will be used repeatedly, after opening the templates enter „**Ulozit**“ (safe) for rewriting the actual template (active) with new set values or it is possible to use „**Ulozit jako**“ (safe as) to create new template.
- ⑩ After the line marking with the respective template, it can be loaded, renamed or deleted
- ⑩ Saving by means of templates considers also individual setting of individual holes (via manual adjustment).

Templates for the line hole function

Active

1

Name

KONFIGURACE 1

ID	Name
1	KONFIGURACE 1

Load

Save

Save as

Rename

Delete

Back

Fig. 20: Hole drilling on line – templates

Holes on the circle

- ⑩ It is used for drilling holes on the circle circumference.
- ⑩ At first, select the plane for drilling
- ⑩ Set the centre coordinates for drilling. It is possible to set any coordinates or the actual coordinates using button „**Nastavit aktualni stred**“ (set actual centre) (see fig. 21: Drilling holes on circle).
- ⑩ Select the number of required holes, circle diameter, initial and final angle.
- ⑩ Automatically re-draws the scene with the display how the task shall look like.
- ⑩ Every entered hole can be edited independently – shift in defined plane axes, set the distance from the centre or the turning angle. This option is achieved by marking the hole in the scene (finger or stylus). Marked hole is green (see fig. 18: Hole drilling on line – edit one point from the scene).
- ⑩ **Caution** during every change of the setting the scene is re-drawn. If for example one hole is shifted to other than defined entry (manually, see point) and then the setting changes, it is automatically re-drawn!
- ⑩ The hole can be deleted from the scene using button „**Odstranit**“ (delete).
- ⑩ After returning to the initial setting, it is possible to use button „**Zpet**“ (back) on the right or mark a location where no hole is drawn in the scene.
- ⑩ As soon as all parts are entered, press button „**Obrabeni**“ (machining) to get back to the machining mode where individual holes can be drilled.




Fig. 21: Drilling holes on circle

Machining

- ⑩ The same principle as in the hole drilling on the line (see chapter **Chyba! Záložka není definována.**).

Templates

- ⑩ The same principle as in the hole drilling on the line (see chapter **Chyba! Záložka není definována.**).

Holes on the nut

- ⑩ It is used for drilling holes on the nut.
- ⑩ At first, select the plane for drilling
- ⑩ Set the centre coordinates for drilling. It is possible to set any coordinates or the actual coordinates using button „**Nastavit aktualni stred**“ (set actual centre) (see fig. 22: Drilling holes on the nut).
- ⑩ Select the number of required holes, number of lines and nut columns, turning, bevelling, spacing of lines and columns.
- ⑩ Automatically re-draws the scene with the display how the task shall look like.
- ⑩ Every entered hole can be edited independently – shift in defined plane axes, set the distance from the centre or the turning angle. This option is achieved by marking the hole in the scene (finger or stylus). Marked hole is green (see fig. 18: Hole drilling on line – edit one point from the scene).
- ⑩ **Caution** during every change of the setting the scene is re-drawn. If for example one hole is shifted to other than defined entry (manually, see point) and then the setting changes, it is automatically re-drawn!
- ⑩ The hole can be deleted from the scene using button „**Odstranit**“ (delete).
- ⑩ After returning to the initial setting, it is possible to use button „**Zpet**“ (back) on the right or mark a location where no hole is drawn in the scene.
- ⑩ As soon as all parts are entered, press button „**Obrabeni**“ (machining) to get back to the machining mode where individual holes can be drilled.




Fig. 22: Drilling holes on the nut

Machining

- ⑩ The same principle as in the hole drilling on the line (see chapter **Chyba! Záložka není definována.**).

Templates

- ⑩ The same principle as in the hole drilling on the line (see chapter **Chyba! Záložka není definována.**).

Programmable points

- ⑩ It is used for entering individual whole to be drilled.
- ⑩ At first, select the plane for drilling
- ⑩ There are two ways of entering the holes for drilling:
 1. It displays the actual tool coordinates and using button „**Pridat bod**“ (add point) to insert the hole in the scene for the actual coordinates (see fig. 23: Programmable points).
 2. It is possible to manually enter the points coordinates by means of buttons „**Nastavit**“ (set) and press „**Pridat bod**“ (add point) at manual entry to insert the hole in the scene.
- ⑩ Every entered hole can be edited independently – shift in defined plane axes. This option is achieved by marking the hole in the scene (finger or stylus). Marked hole is green.
- ⑩ The hole can be deleted from the scene using button „**Odstranit**“ (delete).
- ⑩ After returning to the initial setting, it is possible to use button „**Zpet**“ (back) on the right or mark a location where no hole is drawn in the scene.
- ⑩ As soon as all parts are entered, press button „**Obrabeni**“ (machining) to get back to the machining mode where individual holes can be drilled.
- ⑩ Button „**Reset**“ returns everything into the initial setting




Fig. 23: Programmable points

Machining

- ⑩ The same principle as in the hole drilling on the line (see chapter **Chyba! Záložka není definována.**).

Templates

- ⑩ The same principle as in the hole drilling on the line (see chapter **Chyba! Záložka není definována.**).

Angle of lines

- ⑩ To find out the angle between two lines entered by means of individual points.
- ⑩ At first, select the plane for entering the points for the lines.
- ⑩ Move the tool to the required coordinates which are displayed in positions X and Y in this case.
- ⑩ As soon as the required coordinates are ok, press the button for entering the point for the define line for saving. At first enter points for line A - „**Add point – line A**“ and then points for line B - „**Add point – line B**“.
- ⑩ The angle is automatically counted for every entered point.
- ⑩ It is necessary to enter at least two points for every line for correct result.
- ⑩ Individual points are displayed in the table and after marking one point it can be deleted with button „**Smazat bod**“ (delete point).

ID	X	Y	Line
1	83.800	115.865	A
2	83.800	114.960	A
3	83.800	113.710	A
4	82.780	113.125	B

Fig. 24: Angle between lines

- ⑩ Button „**Reset**“ sets the data in the initial state.

Circle centre

- ⑩ It is used for finding the circle centre entered by means of individual points on the circle circumference.
- ⑩ At first, select the plane for searching the centre.
- ⑩ Use button „**Pridat bod**“ (add point) to add individual points with the actual coordinates (coordinates from encoders) displayed (see fig. 25: Searching for the circle centre).

- ⑩ After entering at least three points, automatically searches for the circle centre and draws in the scene.
- ⑩ It is possible to enter any amount (at least three).
- ⑩ After finding the centre, the circle diameter and centre coordinates are shown.
- ⑩ Button „Reset“ sets everything in the initial state.




Fig. 25: Searching for the circle centre

Machining

- ⑩ After pressing button „Obrabeni“ (machining) it is possible to enter the machining mode.
- ⑩ Use button „Polomer“ (diameter) to switch between the diameter and radius of the found circle.
- ⑩ It further displays the coordinates of the found centre.
- ⑩ It also displays the distance of the tool from the circle centre, and coordinates outside the plane (in this case Z and W) can be reset (set to zero).
- ⑩ If we want to set the coordinates of the found centre in the axis, use button „Prenest vzdalenost“ (transfer distance), which set the coordinates directly on axes (in this case axes X and Y). This changes the setting of the axes in active scale (for more see chapter **Chyba! Záložka není definována.**).




Fig. 26: Searching for the circle centre – machining mode

Setting

- ⑩ Setting is entered via menu by button „Setting“ (see chapter **Chyba! Zázločka není definována.**).




Fig. 27: Setting

- ⑩ It displays four options for the application setting (see fig. 27: Setting).

Basic setting

- ⑩ Setting time for the device.
- ⑩ Setting the device type – miller, lathe, grinder. This setting affects the tool function (see chapter **Chyba! Záložka není definována.**).
- ⑩ In case of setting the device type lathe or grinder it is impossible to display functions for drilling holes or searching for line angle or circle centre. It is impossible to see other functions (see fig. 7: The extension menu functions for the device type miller).
- ⑩ The setting of displayed units – mm or inches.
- ⑩ Setting the application language (currently cannot change).
- ⑩ Factory setting restoring – the machine is in the state after purchase. **Caution** deletes all saved options and setting created by the user!!!
- ⑩ User setting – it is possible to back-up or load the current application state, i.e. All saved options and setting created by the user.
- ⑩ About the program – it displays the version of the application and date of the version occurrence.

Basic settings

Time

08:38

Change

Type of device

Milling machine

Change

Settings of units

mm

Change

Back

<

>

Main screen

Fig. 28: Basic setting

Basic settings

Language

English

Change

Reset to factory settings

Restore

User settings

Save

Load

About the program

Display

Back

<

>

Main screen

Fig. 29: Basic setting

Setting the axes

- ⑩ It is used for setting the parameters for individual axes.
- ⑩ After pressing button „**Nastaveni os**“ (setting axes) the axis selection is displayed which requires the setting (see fig. 30: Axis displayed – axis selection for the setting).
- ⑩ After axis selection a setting for the selected axis displays.
- ⑩ The axis selection can be changed any time by means of top right button which displays the actually set axis (see fig. 31: Axis setting – linear mode).




Fig. 30: Axis displayed – axis selection for the setting

Settings of axis		Current axis: X
Movement to reference point	No	Change
Machine reference	0.0050	Change
Move to machine reference	Yes	Change
Averaging	1	Change
Tolerance	0.0050	Change
Speed of movement	m/min	Change

Fig. 31: Axis setting – linear mode

Settings of axis		Current axis: X
Mode of the axis	Linear	Change
Direction	+	Change
Encoder resolution	0.0050	Change
Display resolution	0.005	Change
Lin.compensation (mm/m)	0.0000	Change

Fig. 32: Axis setting – linear mode

Settings of axis		Current axis: X
Mode of the axis	Angular	Change
Direction	+	Change
Pulses/360°	1024	Change
Display resolution	0.5	Change
Lin.compensation (°/360°)	0.0000	Change
Clear after 360°	Yes	Change
Back < > Main screen		

Fig. 33: Axis setting – angle mode

Settings of axis		Current axis: X
Movement to reference point	No	Change
Machine reference	0.0050	Change
Move to machine reference	Yes	Change
Averaging	1	Change
Tolerance	0.0050	Change
Speed of movement	m/min	Change
Back < > Main screen		

Fig. 34: Axis setting – angle mode

Axis mode

- ⑩ Axis mode selection:

- ↘ Linear.
- ↘ Angle.
- ⑩ According to selected mode, other settings are displayed for the axis.

Direction

- ⑩ Linear and angle axis mode.
- ⑩ It defines if the positive direction of the displayed deduction in the defined axis is compliant (+) with positive direction of the encoder reading, or opposite (-).
- ⑩ Direction can be set
 - ↘ Positive (+).
 - ↘ Negative (-).

Encoder resolution

- ⑩ Axis linear mode.
- ⑩ Options for entering encoder resolution.
- ⑩ It defines the resolution abilities of the encoder (defined by the manufacturer or encoder type) in millimetres.
- ⑩ It is possible to enter any value.

Display resolution

- ⑩ Linear and angle axis mode.
- ⑩ It defines the value for changing the data for the defined axis, and also the decimal places of read value to be displayed.
- ⑩ It is possible to select the display resolution
 - ↘ 1.0 – 0.5 – 0.1 – 0.05 – 0.01 – 0.005 – 0.001 – 0.0005

Linear correction

- ⑩ Linear and angle axis mode.
- ⑩ It is used for compensating errors which may appear during measuring.
- ⑩ The errors can indicate the values different from real values.
- ⑩ The errors can result from the machine inaccuracy, e.g. desk deformation during loading with worked material.
- ⑩ It is possible to enter any value.

Resetting after 360°

- ⑩ Axis angle mode.
- ⑩ After every turn by 360° the angle value can be set to zero.
- ⑩ This option is currently inactive.

Moving to the reference point

- ⑩ Linear and angle axis mode.
- ⑩ The option for moving to the reference point after the program start.
- ⑩ If I choose I want to move to reference point on the defined axis, after the program start deactivate all buttons except for the axes setting, and the title „Ref“ appears on the respective axis (see fig. 35: Moving to the reference point).
- ⑩ The button for axes setting is here because it can be switched off on the defined axis in case of a problem, and the readout is commonly started after the program restart.
- ⑩ As soon as the encoder moves to the reference point, „Ok“ appears on the defined axis.
- ⑩ If other axis do not include the setting of the reference point, the program starts and displays the values from the sensors.
- ⑩ If the movement to reference points is set on other axis, it is displayed on another axis in the order title „Ref“ and repeat the procedure until all reference points are reached.




Fig. 35: Moving to the reference point

Machine reference

- ⑩ Linear and angle axis mode.
- ⑩ This option is currently inactive.

Moving to the machine reference

- ⑩ Linear and angle axis mode.
- ⑩ This option is currently inactive.

Averaging

- ⑩ Linear and angle axis mode.
- ⑩ It is used for the diameter display of the last values from the encoder to eliminate random errors.
- ⑩ It is possible to set averaging from the last values
 - ↘ 1 – 2 – 4 – 8 – 16
- ⑩ Setting the averaging results in increased start of the displayed value. If we move the tools and stop, we can see the value 'reaching'. It must be considered.

Tolerance

- ⑩ Linear and angle axis mode.
- ⑩ This option is currently inactive.

Feed speed

- ⑩ Linear and angle axis mode.
- ⑩ It is used for displaying the shift speed on the defined axis on the initial screen (see chapter **Chyba!** **Záložka není definována.** - point 4).
- ⑩ It is possible to set speeds
 - ↘ m/min
 - ↘ mm/min
 - ↘ mm/s
 - ↘ Do not display – if I do not want to know the speed related data

Axes adding

⑩ Every axis enables to define the adding of values from other axes multiplied by the real coefficient **k**, where **k** is subject to $-1 \leq k \leq 1$.

⑩ The coefficients are defined as cosines function value for the angle value recorded in the angle planes. For example axis X is subject to formula

$$X = X + Y \times \cos(\beta_x) + Z \times \cos(\gamma_x) + W \times \cos(\delta_x)$$

⑩ Values β_x , γ_x , δ_x represent the respective angles. The formula represents in line the adding of Y axis value multiplied by the function value cosine for angle β_x , value of axis Z multiplied with function value cosine for angle γ_x and finally value of axis W multiplied with function value cosine for angle δ_x to axis value X.

⑩ In the initial setting the angles equal to 90° , which in case of axis X results in relation:

$$X = X + Y \times \cos(90^\circ) + Z \times \cos(90^\circ) + W \times \cos(90^\circ)$$

⑩ Values of axis X do not change with adding other axes (function cosine for angle 90° the zero values).

⑩ Additionally to the buttons for setting the angles for individual axes, there are buttons on the left for covering and displaying individual axes. The change of the setting is indicated on the main screen.

Addition of axes

	X*cos(a)	+ Y*cos(b)	+ Z*cos(c)	+ W*cos(d)
X=				
	90.00		90.00	90.00
Hide	Set		Set	Set
Y=	90.00			
	Set		90.00	90.00
Hide			Set	Set
Z=	90.00	90.00		
	Set	Set		90.00
Hide				Set
W=	90.00	90.00	90.00	
	Set	Set	Set	
Hide				

Back

Main screen

Fig. 36: Axes adding

Programmable buttons

⑩ The main screen enables setting three buttons according to won requirements.

⑩ It includes buttons three to five (see fig. 37: Programmable buttons).

⑩ It is possible to set under any of the three buttons in setting (see fig. 27: Setting) the option:

↘ Scale

- ↘ Tool
- ↘ Half
- ↘ Calculator




Fig. 37: Programmable buttons

1. Extending functions

- ⑩ If the readout is adapted to it, it is possible to use other special functions.

Touch probe

- ⑩ The extension functions for the touch probe can be seen between other functions in the menu (see).





Fig. 38: Menu – touch probe

- ⑩ After opening it includes four new function for use with 2D touch probe (see fig. 39: Touch probe function)


1. Centre of abscissa.
2. Circle centre.
3. workpiece centre.
4. Workpiece edge.



The image shows a software menu titled "Touch probe". It contains four main function buttons arranged in a 2x2 grid: "Centre of line", "Centre of circle", "Centre of workpiece", and "Edge of workpiece". At the bottom, there are two navigation buttons: "Back" on the left and "Settings" on the right.

Touch probe	
Centre of line	Centre of circle
Centre of workpiece	Edge of workpiece
Back	Settings

Fig. 39: Touch probe function



The image shows a software menu titled "Probe settings". It contains four settings rows, each with a label, a value field, and a "Change" button. The settings are: Diameter (10.000), Plane (XY), and Compensation (On). Below these is a "Calibration on circle" label with a "Calibrate" button. At the bottom is a "Back" button.

Probe settings		
Diameter	10.000	Change
Plane	XY	Change
Compensation	On	Change
Calibration on circle		Calibrate
Back		

Fig. 40: Touch probe setting

Setting

⑩ In the bottom right (see fig. 39: Touch probe function) is setting for the touch probe which enables setting

↘ Probe diameter

↘ The plane where the probe shall be used

↘ Compensation – setting if it is possible to consider the compensation during the probe entry on the workpiece. The compensation can be achieved by means of probe calibration on the circle.

↘ The calibration on the circle – for the probe calibration to reach the lowest possible error caused by the touch probe.

⑩ **Caution** – in case of changing the plane setting, it is necessary to recalibrate the touch probes on the circle!!! The compensation related data are automatically reset..

Calibration on the circle

⑩ The calibration on the circle is used for finding values for the deviation compensation of the touch probe in selected axes (according to the set plane).

⑩ Correct calibration must be completed in nine simple steps with some steps repeated.

⑩ The actually performed step is in the top right (see fig. 41: Touch probe – calibration on the circle – step 1). It is the first step from nine.

⑩ Individual steps are defined by a simple guide in the form of text on yellow base on the right.

⑩ Calibration procedure:

1. It is necessary to move the probe on the body on the circle circumference . It does not matter if it is on the internal or external side of the circle only if one method is selected (e.g. external) it must be observed for the whole calibration period! individual points are entered by means of button „**Potvrđit**“ (confirm). it is necessary to enter three points.


2. after entering three points on the circle circumference the found circle is automatically drawn with the centre. Now it is necessary to physically turn the touch probe by 90° in the clamping mechanism. when the probe turns, press button „**Dalsi krok**“ (next step) (see fig. 42: Touch probe – calibration on the circle – step 2).

3. repeat point 1. and then point 2. three times.

4. Finally, four centres are found with the compensation values. In ideal case, all four centres are the same and the compensation is zero (see fig. 43: Touch probe – calibration on the circle – last step).

5. The compensation value is automatically saved for next probe use and the extended functions.

Touch probe - Calibration on circle
1 / 9



Step 1

Move the probe to 3 selected points on the circle. Press the Confirm button in each point.

Current point

X

83.915

Y


109.385

Confirm

Back

Fig. 41: Touch probe – calibration on the circle – step 1

Touch probe - Calibration on circle
2 / 9



Step 2

Turn the probe 90 degrees in the clamping mechanism. Then continue to the next step.

Found centre

X

84.585

Y

107.290

1 / 4

Back

Next step

Fig. 42: Touch probe – calibration on the circle – step 2

40





Fig. 43: Touch probe – calibration on the circle – last step

Centre of abscissa

- ⑩ It is used for finding the abscissa centre entered by means of two points on the touch probe.
- ⑩ After the probe reaches the required coordinate, press button „**Potvrdit**“ (confirm) (see fig. 44: Touch probe – abscissa centre) the first point is drawn in the scene.
- ⑩ After reaching the second required coordinate with the probe and pressing button for the confirmation, the second point is saved and the found abscissa is drawn with the centre (see fig. 45: Touch probe – abscissa centre – found centre).
- ⑩ It displays the radius (diameter) value of abscissa, the coordinates of the found centre, and it displays data on the line centre distance from the touch probe coordinates.
- ⑩ The diameter value can be switched with buttons „**Polomer/Prumer**“ (diameter/ radius) for the defined abscissa.
- ⑩ Button „**Vnejsi/Vnitřni**“ (external/ internal) is used for the diameter value treatment according to the way we moved the touch probe on individual line coordinates. They can be from external or internal side.
- ⑩ Button „**Zapnuto/Vypnuto**“ (on/off) for the compensation edits values of the centre coordinates as per the defined compensation received during the calibration of the touch probe on the circle (see chapter **Chyba! Záložka není definována.**).
- ⑩ Button „**Reset**“ sets everything into the initial setting.
- ⑩ Button „**Prenest střed**“ (transfer centre) transfers the coordinates of the defined axis centre.

Touch probe - Centre of circle



Approaching

Compensation

Current position

X 82.890

Y 103.590


Centre

X ---

Y ---

Fig. 44: Touch probe – abscissa centre

Touch probe - Centre of line



Approaching

Compensation

Distance from the centre

X -2.905

Y -4.530

-0.018

Centre

X 85.795

Y 108.118

Fig. 45: Touch probe – abscissa centre – found centre

Circle centre

- ⑩ It is used for finding the circle centre entered by means of three points on the touch probe.
- ⑩ After the probe reaches the required coordinate, press button „**Potvrdit**“ (confirm) (see fig. 46: Touch probe – circle centre) the first point is drawn in the scene.
- ⑩ After reaching the second and third required coordinate with the probe and confirming the coordinates, the found circle is drawn with the centre (see fig. 47: Touch probe – circle centre – found centre).
- ⑩ It displays the radius (diameter) value of circle, the coordinates of the found centre, and it displays data on the circle centre distance from the touch probe coordinates.
- ⑩ The diameter value can be switched with buttons „**Polomer/Prumer**“ (diameter/ radius) for the defined circle.
- ⑩ Button „**Vnejsi/Vnitřni**“ (external/ internal) is used for the diameter value treatment according to the way we moved the touch probe on individual circle coordinates. They can be from external or internal side.
- ⑩ Button „**Zapnuto/Vypnuto**“ (on/off) for the compensation edits values of the centre coordinates as per the defined compensation received during the calibration of the touch probe on the circle (see chapter **Chyba! Záložka není definována.**).
- ⑩ Button „**Reset**“ sets everything into the initial setting.
- ⑩ Button „**Preneš střed**“ (transfer centre) transfers the coordinates of the defined axis centre.

Touch probe - Centre of line



Approaching	Outer
Compensation	On
Current position	Confirm
X	84.775
Y	106.585
Radius	---
Centre	
X	---
Y	---

Fig. 46: Touch probe – circle centre





Fig. 47: Touch probe – circle centre – found centre

Workpiece centre

- ⑩ It is used for finding the rectangular (square) workpiece entered by means of four points on the touch probe.
- ⑩ After the probe reaches the required coordinate, press button „**Potvrdit**“ (confirm) (see fig. 48: Touch probe – workpiece centre) the first point is drawn in the scene.
- ⑩ After reaching the remaining three points (each on one side of the workpiece) and confirming the coordinates, the found workpiece is drawn with the centre (see fig. 49: Touch probe – workpiece centre – found centre).
- ⑩ It displays value of coordinates of the found centre, and it displays data on the workpiece centre distance from the touch probe coordinates.
- ⑩ Button „**Zapnuto/Vypnuto**“ (on/off) for the compensation edits values of the centre coordinates as per the defined compensation received during the calibration of the touch probe on the circle (see chapter **Chyba! Záložka není definována.**).
- ⑩ Button „**Reset**“ sets everything into the initial setting.
- ⑩ Button „**Prenest stred**“ (transfer centre) transfers the coordinates of the defined axis centre.

Touch probe - Centre of workpiece



Let the probe touch the workpiece from 4 sides . Touch every side one time only!

Current position

X 70.705

Y 100.510


Confirm

Back

Reset

Fig. 48: Touch probe – workpiece centre

Touch probe - Centre of workpiece



Compensator

On

Distance from the centre

X 0.610

Y -3.075

Centre

X 73.930

Y 102.723

Back

Reset

Transfer distance

Fig. 49: Touch probe – workpiece centre – found centre

Workpiece edge

- ⑩ It is used for finding the rectangular (square) workpiece edge entered by means of two points on the touch probe.
- ⑩ At first set the searched edge with button „**Zmenit**“ (change) at the searched edge (see fig. 50: Touch probe – workpiece edge)
- ⑩ Move the touch probe on the workpiece walls to find the edge.
- ⑩ After the probe reaches the required coordinate, press button „**Potvrdit**“ (confirm) to draw their position and found centre of the workpiece edge (see fig. 51: Touch probe – workpiece edge – found centre).
- ⑩ It displays value of coordinates of the found edge centre, and it displays data on the workpiece edge centre distance from the touch probe coordinates.
- ⑩ Button „**Zapnuto/Vypnuto**“ (on/off) for the compensation edits values of the edge centre coordinates as per the defined compensation received during the calibration of the touch probe on the circle (see chapter **Chyba! Záložka není definována.**).
- ⑩ Button „**Reset**“ sets everything into the initial setting.

Touch probe - Edge of the workpiece

Let the probe touch the workpiece from 2 sides, where you want to find the edge. Touch every side one time only!

Desired edge Change

Left down

Current position Confirm

X 74.540

Y 99.650

Back Reset

Fig. 50: Touch probe – workpiece edge

- ⑩ Button „**Prenest stred**“ (transfer centre) transfers the coordinates of the defined axis centre.




Fig. 51: Touch probe – workpiece edge – found centre

2. System update

- ⑩ To update the system TSMAX to higher version of the system by means of PC it is necessary to install program „**TSMAX Update PC**“.
- ⑩ Connect the readout unit by means of series interface (RS 232) to PC and start program “**TSMAX Update PC**“.
- ⑩ It displays the initial screen of the update program (see fig. 52: System update – initial screen).
- ⑩ The lower side of the window includes the status line which informs on the whole update procedure.

TSMAX update
for PC v1.1

Aktualizace systemu Obnoveni systemu

Aplikace **Zvolit**

Licence **Zvolit**

Aktualizovat

* Kliknutim na Aktualizovat provedete aktualizaci indikacni jednotky polohy TSMAX

Seriovy port **Prohledat** **Pripojit**

COM: Uzavren | Aplikace: Nezvolena | Licence: Nezvolena

Fig. 52: System update – initial screen

- ⑩ At first press button „**Prohledat**“ (search) to search all series ports used in PC. Then select the specific series port where the readout unit is connected.
- ⑩ Now it is necessary to select the application file for the update and the license file using buttons „**Zvolit**“ (select).
- ⑩ Finally press button „**Pripojit**“ (connect).
- ⑩ If everything is ok, the button for „**Aktualizovat**“ (update) is available (see fig. 53: System update – prepared for update).

TSMAX update

for PC v1.1

Aktualizace systemu Obnoveni systemu

Aplikace

C:/Users/Uzivatel/Desktop/Update PC/Test_old

Zvolit

Licence

C:/Users/Uzivatel/Desktop/Update PC/TSMAX.lic

Zvolit

Aktualizovat

* Kliknutim na Aktualizovat provedete aktualizaci indikacni jednotky polohy TSMAX

Seriový port

COM6

Prohledat

Odpojit

COM: COM6 - Pripojeno | Aplikace: Zvolena Test_old | Licence: Zvolena TSMAX.lic

Fig. 53: System update – prepared for update

- ⑩ After the update the file transfer commences into the application (see fig. 54: System update – update in progress).




Fig. 54: System update – update in progress

- ⑩ After completing the system update, new status report displays to restart the readout unit (see fig. 55: System update – update completed).
- ⑩ After the readout unit restart, the system should automatically start with program TSMAX.




Fig. 55: System update – update completed

3. System restart

- ⑩ To update the system TSMAX to higher version of the system by means of PC it is necessary to install program „**TSMAX Update PC**“ (for the same program see. Chapter **Chyba! Záložka není definována.**, only the second chapter).
- ⑩ Connect the readout unit by means of series interface (RS 232) to PC and start program “**TSMAX Update PC**”.
- ⑩ It displays the initial screen of the update program (see fig. 56: System restart – initial screen).




Fig. 56: System restart – initial screen

- ⑩ The lower side of the window includes the status line which informs on the whole system restart.
- ⑩ At first press button „**Prohledat**“ (search) to search all series ports used in PC. Then select the specific series port where the readout unit is connected.
- ⑩ Finally press button „**Pripojit**“ (connect).
- ⑩ If everything is ok, the button appears with the required readout unit restart (see fig. 57: System restart – connection of serial port).
- ⑩ After manual restart button „**Obnovit**“ (restart) is available. The system restart commences.




Fig. 57: System restart – connection of serial port

- ⑩ After completing the system restart information is displayed on the completion (see fig. 58: System restart – completion).




Fig. 58: System restart – completion

List of pictures

Fig. 1: D-SUB socket	4
Fig. 2: Electric specification of sensor signals	5
Fig. 3: Digital readout scheme	5
Fig. 4: Initial screen	7
Fig. 5: Initial screen – switching diameter/ radius for the device type lathe	7
Fig. 6: Function menu	8
Fig. 7: The extension menu functions for the device type miller	8
Fig. 8: Function for searching the angle between the line (abscissa) and the selected plane	9
Fig. 9: Function for searching the abscissa centre between two points	10
Fig. 10: Function half	10
Fig. 11: Scale - Review screen	12
Fig. 12: Scale – list of saved scales.	12
Fig. 13: Tool – review screen for tool type miller.	14
Fig. 14: Tool – review screen for tool type lathe	15
Fig. 15: Calculator.	16
Fig. 16: Calculator – value transfer.	16
Fig. 17: Drilling holes on the line	17
Fig. 18: Hole drilling on line – edit one point from the scene	18
Fig. 19: Hole drilling on line – machining mode	19
Fig. 20: Hole drilling on line – templates	20
Fig. 21: Drilling holes on circle	21
Fig. 22: Drilling holes on the nut	22
Fig. 23: Programmable points.	24
Fig. 24: Angle between lines.	25
Fig. 25: Searching for the circle centre.	26
Fig. 26: Searching for the circle centre – machining mode	27
Fig. 27: Setting	27
Fig. 28: Basic setting.	28
Fig. 29: Basic setting.	29
Fig. 30: Axis displayed – axis selection for the setting.	30
Fig. 31: Axis setting – linear mode	31
Fig. 32: Axis setting – linear mode	31
Fig. 33: Axis setting – angle mode	32
Fig. 34: Axis setting – angle mode	32
Fig. 35: Moving to the reference point	34
Fig. 36: Axes adding	36
Fig. 37: Programmable buttons.	37
Fig. 38: Menu – touch probe.	38
Fig. 39: Touch probe function.	39
Fig. 40: Touch probe setting	39
Fig. 41: Touch probe – calibration on the circle – step 1	41
Fig. 42: Touch probe – calibration on the circle – step 2	41
Fig. 43: Touch probe – calibration on the circle – last step	42
Fig. 44: Touch probe – abscissa centre	43
Fig. 45: Touch probe – abscissa centre – found centre	43
Fig. 46: Touch probe – circle centre	44
Fig. 47: Touch probe – circle centre – found centre	45
Fig. 48: Touch probe – workpiece centre	46
Fig. 49: Touch probe – workpiece centre – found centre	46
Fig. 50: Touch probe – workpiece edge	47

Fig. 51: Touch probe – workpiece edge – found centre	48
Fig. 52: System update – initial screen	49
Fig. 53: System update – prepared for update	50
Fig. 54: System update – update in progress	50
Fig. 55: System update – update completed	51
Fig. 56: System restart – initial screen	52
Fig. 57: System restart – connection of serial port	53
Fig. 58: System restart – completion	53